

Order Through CTA, Turn in Unserviceables

YOU CAN NOW ORDER AIMING LASERS THROUGH THE STANDARD SUPPLY SYSTEM!


NO MORE RED TAPE, THANK GOODNESS!



AIMING LASERS WITH LINE ITEM NUMBERS (LIN) J03261, J68403 AND A44066 ARE NOW AUTHORIZED BY TABLE 63 OF CTA 50-909.

THAT MEANS YOU NO LONGER NEED TO DO AN OPERATIONAL NEEDS STATEMENT TO GET ADDITIONAL AIMING LASERS.

YOU CAN JUST ORDER MORE WITH A FUNDED REQUISITION THROUGH THE ARMY SUPPLY SYSTEM!



Here's what is available:

LIN	Model	NSN
J03261	AN/PEQ-15 (tan)	5855-01-577-7174
J03261	AN/PEQ-15A (black)	5855-01-535-6166
J03261	AN/PEQ-15A (green)	5855-01-579-0062
J68403	AN/PEQ-14 (black)	5855-01-538-0191
J68403	AN/PEQ-14 (tan)	5855-01-571-1258
A44066	LA-8/P (right-handed)	5860-01-558-4706
A44066	LA-8/P (left-handed)	5860-01-564-8167

Turning in Aiming Lasers

If you have unserviceable aiming lasers, you need to turn them in so they can be fixed and returned to the field. Your property book officer should report them to the National Inventory Control Point (NICP) B14, using an FTE (report of excess) and following the instructions in Chap 7 of AR 725-50, *Requisition and Issue of Supplies and Equipment*.

The NICP will respond with final disposition instructions through an FTR (reply to report of excess) with exception data. The exception data require the unit to provide a copy of the DD Form 1348 that documents the demilitarization of the aiming light and is signed by the DOL or DLA Disposition Services. The serial number must be included on the 1348.

Order a replacement by submitting a funded requisition through the standard Army supply system.

If you have questions about any aiming lasers, contact Jeffrey York at DSN 312-781-1344, (586) 282-1344, or email:

jeffrey.l.york2.civ@mail.mil

M120A1 Mortar...

REMOVE CLAMP FOR INSPECTION

TM 9-1000-202-14, *EVALUATION OF CANNON TUBES*, SAYS MORTAR REPAIRMEN NEED TO CHECK THE M120A1'S CANNON FOR VISIBLE DENTS, OUT-OF-ROUNDNESS AND EXTERNAL GOUGING.

Unfortunately, you can't do that without removing the barrel clamp assembly. And the 120mm mortar's TM 9-1015-256-13&P mentions nothing about that.

So, this TM will be changed to specify that the clamp must first be removed before the cannon is checked. But, in the meantime, note that in your -13&P, repairmen. Barrel clamp instructions can be found in TM 9-1230-205-13&P

Questions? Contact TACOM's Erik Jensen at (586) 282-1220, DSN 786-1220, or email:

erik.s.jensen4.civ@mail.mil

Remove barrel clamp before inspecting cannon

