

DON'T GO CAPLESS!

HEY, CAN YOU CUT DOWN ON THE REFLECTION?

THAT'S LIKE 'PLEASE SHOOT HERE' TO THE ENEMY!

NOT MY FAULT, DUDE.

YOU TOOK OFF MY ANTI-REFLECTIVE CAP. BAD MOVE.



THE ANTI-REFLECTIVE CAP SERVES TWO FUNCTIONS FOR THE M68 REFLEX SIGHT...

- It prevents a reflection from signaling your position to the enemy. That could mean the difference between life and death to you on the battlefield.
- It protects the M68's lens from getting scratched up. If the lens gets too scratched up, you can't see through it and the sight becomes unusable.

Those are two very good reasons to keep the anti-reflective cap on at all times. But Soldiers keep removing the cap and losing it because the cap makes it harder to use the M16 rifle's BUIS (backup iron sight).


Don't do it. You're just shortening the life of the M68 and maybe yours, too. If the cap has disappeared, order a new one with NSN 6650-01-479-5386.

Get Newest TM

Make sure you have the newest TM for the M68, TM 9-1420-413-13&P (Mar 08). It covers the M68 Comp M2, NSN 1240-01-411-1265, and M68 Comp M4/M4S, NSN 1240-01-540-3690. It's online at the LOGSA ETM website:

<https://www.logsa.army.mil/etm/>

Some units report getting M68s with the old TM 9-1420-413-12&P. It's way out of date, so make sure you're using the newest edition.



Leave anti-reflective cap on at all times