



M1101/M1102 Trailer Shock NSN

Get a new shock absorber for your M1101 and M1102 cargo trailers using NSN 2510-01-554-1785. NSN 2510-01-190-3862, which is shown as Item 6 of Fig 14 in TM 9-2330-392-13&P (Dec 12), is now a terminal item.

TURN IN ALL BASIC M967, M969, AND M970 FUEL TANKERS

All basic M967, M969, and M970 5,000-gal fuel tankers have a zero percent maintenance expenditure limit (MEL). So they must be turned in right away to DLA Disposition Services (formerly known as DRMO). Get replacement instructions from TACOM LCMC's trailer item manager, Breia Kilgo. You can reach her at DSN 786-6800, 586-282-6800, and email:

breia.n.kilgo.civ@mail.mil

M151 Scope with LFU/ARD

Because of safety regulations for eye protection, the M151 spotting scope, NSN 6650-01-504-8456, is no longer available. If you need a new scope, order NSN 6650-01-557-7444, which combines the scope with the laser filter unit (LFU)/anti-reflective device (ARD) as one assembly. Remember, you can order the M151 only if you are authorized the M110 sniper system.

M68 Sight Cap NSN

The lens cap for the M68 reflex sight is important for two reasons: It prevents a reflection that can signal your position and it protects the lens from getting scratched up. Unfortunately, the cap often disappears. Order extras with NSN 6650-01-479-5386. And make sure you have a copy of TM 9-1420-413-13&P (Mar 08), which covers both the M68 Comp M2 and M4/M4S.

SERVICE STRIPES AND BARS

Look sharp for formal occasions. Here are the NSNs for service stripes and overseas service bars worn with the new blue Army service uniform (ASU):

Item	Size	Qty	NSN 8455-
Overseas service bars	Large	85	01-571-2906
Overseas service bars	Small	100	01-571-2914
Service stripes	Large	60	01-571-2923
Service stripes	Small	85	01-571-2927

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life *right now* on the Condition of Your Equipment?