


# No More Lube for 5th Wheel Plates



The new M1070A1 HETs have an upgrade that you might not know about, drivers. The 5th wheel now comes equipped with new plates that take **no lubrication**.

You heard it right! **No lube!** In fact, if you lube the non-lubrication plates, they'll collect sand, dirt and grit that will severely damage the plates.

You should continue putting a coat of GAA on the top surface of the 5th wheel's ramps, just like before. Before hookup, be sure to remove any grease on the M1000 semitrailer that would come into contact with the 5th wheel's non-lubrication plates.



Replacement plates are available as part of a kit, NSN 5340-01-603-7792. Both the left and right plate and 18 mounting screws come with the kit.