

D7R II Dozer PMCS Error

Operators, forget about using the blade float indicator mentioned in PMCS Step 26 of TM 5-2410-241-10. That indicator is an option only on commercial D7R dozers, not the military version. Make a note until the -10 TM is updated.

How to Find LOGSA's MMDF

The Logistics Support Activity (LOGSA) keeps the Maintenance Master Data File (MMDF) in the Logistics Information Warehouse (LIW). Here's how to find it. First, go to LIW at:

<https://liw.logsa.army.mil/>

After you sign in, click on **App Warehouse**. In the "Application Category" drop-down list, pick **MMDF**. Click **Create Shortcut** for the LIW RSRCs app. This adds an LIW RSRCs icon to your LIW portal. From then on, picking that icon gives you a list of LIW resources, including the MMDF. For MMDF help, email:

usarmy.redstone.logsa.mbx.mmddf@mail.mil

New Sentinel IETM Coming

A new Sentinel IETM will soon be hitting the field. But if you don't update your pubs account, you won't get it. Update your DA Form 12-series at:

<https://dol.hqda.pentagon.mil/ptclick/index.aspx>

Enter EM 0096, TM 9-1430-SENTINEL, IDN 323475, and the number of copies you'll need. The new IETM uses the IADS format, instead of the previous AIMSS format. For information on how to use IADS, go to:

<https://iads.redstone.army.mil>

ATP 4-0.6 Offers LIS Support

A new Army Techniques Publication (ATP) 4-0.6, *Techniques for Sustainment Information Systems Support*, was released in April 2013. This ATP from the Combined Arms Support Command (CASCOM) Enterprise System Directorate (ESD) covers field level support for Logistics Information Systems (LIS).

Download the ATP from the milSuite forum: <https://www.milsuite.mil/book/thread/100201> or at: http://armypubs.army.mil/doctrine/DR_pubs/dr_a/pdf/atp4_0x6.pdf

Turn in M202 Rocket Launcher

If you still have M202 rocket launchers, NSN 1055-00-021-3909 and LIN L45250, turn them in now. They're obsolete.

Ship them to:

DODAAC: W562RP

RIC: BA4

DLA Disposition Services Anniston
Anniston Army Depot
7 Frankford Ave, Bldg 282
Anniston, AL 36201-4199

MRAP Annual Service Kits

Semiannual services are no longer required for any of the MaxxPro variants, so make a note in the vehicle TMs until they're updated. However, PMCS and annual services **are** still required. So get the annual service kit for the M1224 MaxxPro base model with NSN 2990-01-570-3792. Use NSN 2990-01-578-9655 to get an annual service kit for these MRAP variants: M1234 Plus, M1234A1 Plus ambulance, M1235 Dash, M1235A1 Dash DXM and M1235A2 Dash DXM ambulance.

SNAG THE PACKAGING BULLETIN

AMC's *Packaging Bulletin* gives a snapshot of what's happening around the Army packaging community. You'll also learn about the latest in packaging testing, development and new materials. To subscribe, email your request to: eric.j.cowan6.civ@mail.mil

You can request access to past issues of the *Packaging Bulletin* by visiting:

https://collab.aep.army.mil/sites/Packaging_Bulletin/default.aspx

Correct M26 Decon Fuel Can Position

If you go by some of the illustrations throughout TM 3-4230-238-10 and -23&P on positioning the M26's fuel can, you could end up with a fire. That position allows the metal braided fuel lines to touch the burner, melt their rubber interior and leak. The fuel can should be installed so that its fuel lid is on the opposite side of the burner to keep the fuel lines from touching the burner. Questions? Contact TACOM's Emily Santiago at DSN 786-1702, (586) 282-1702, or email: emily.e.santiago2.civ@mail.mil

FMTV Torque Rod Seal Kit

Page 61 of PS 726 (May 13) listed NSN 2510-01-499-5596 for the FMTV's torque rod seal kit (with tool). That NSN is now a terminal item. Get the kit with NSN 2510-01-525-7576.

REPLACE M26 IUID STICKER

The M26 decon's item unique identification (IUID) sticker isn't durable enough to last as long as the M26. TACOM is replacing the sticker with an IUID plate. To get plates for your M26s, follow the instructions in MAM 13-034, which you can find at: <https://tulsa.tacom.army.mil/> Include POC and phone number, installation, shipping address, and the M26 serial numbers. MWO 3-4230-238-23 gives instructions on how to install the plate. If you've already responded to MAM 13-034, you don't need to do anything further.

M149A1/A2 Trailer Elbow Pipe

Get the 90-degree elbow pipe for the faucet on your M149A1/A2 water trailer with NSN 4730-00-253-5765 (M149A1 and early configuration M149A2) or NSN 4730-01-433-2623 (current configuration M149A2). NSN 4730-00-221-4997, which is shown as Item 16 in Fig 28 of TM 9-2330-267-14&P (Jul 91), brings a 45-degree elbow pipe that won't work. Make a note until these NSNs appear in the new TM 9-2330-367-13&P, which is scheduled for print in the near future.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?