

PIN GIVES BEFORE LOCKS

NEED TO REPLACE THE SHEAR PIN ON YOUR PLS OR HEMTT LHS TRUCK?

I'VE GOT YOUR NSNS RIGHT HERE!




PLS AND HEMTT TRUCKS THAT HAVE ENHANCED CONTAINER HANDLING UNITS (E-CHU) WITH SERIAL NUMBERS 1422 AND ABOVE HAVE REDESIGNED LOWER STORAGE LOCKS.

IF THOSE LOCKS **AREN'T** DISENGAGED BEFORE RAISING THE E-CHU FROM ITS STOWED POSITION, A SHEAR PIN INSIDE EACH LOCK IS DESIGNED TO SNAP.

THAT PREVENTS ANY **DAMAGE** TO THE E-CHU.



SO CHECK FOR **SNAPPED** OR **MISSING** SHEAR PINS **BEFORE** EACH DAY'S RUN.



IT'S UP TO YOU TO REPLACE THOSE BROKEN SHEAR PINS WHEN THAT HAPPENS.



REPLACE A MISSING OR DAMAGED PIN WITH THESE NSNS:

Item	NSN
Shear screw	5305-01-440-3666
Locknut	5310-01-457-3244
Washer	5310-01-506-0517