

Longer Time Between Services



DO YOU HAVE AN
AUTOMATED INTEGRATED
SURVEY INSTRUMENT (AISI),
NSN 6675-01-503-3579,
MANAGED BY CECOM?

YOU DO?
THEN
**LISTEN
UP!**

Until recently, your AISI required contractor service once every 3 years. Now the manufacturer of the AISI, Trimble Navigation, Ltd., has extended the service interval to once every 5 years. The extension covers all AISIs managed by CECOM.

AISIs under this contract have a sticker that shows the month and year when the next service is due. Because the service date is set for every 3 years, the sticker needs to be updated. Add two years to the date shown on the sticker and write the new service due date on the sticker.

When To Get Service

So, how do you know when your AISI needs contractor service? Look at the month and year on the sticker. The sticker always reflects a 3-year interval service due date. To get the new 5-year interval service due date, simply add 2 years to the date shown. For example, if the sticker reads April 2014, then the new service due date is April 2016.


Why Extend the Service Interval?

The AISI has an internal battery that supplies power to store data and firmware/software. The manufacturer of this battery has increased its operating life. That in turn has increased the AISI's time between services to 5 years.

As long as you inspect and maintain the AISI like it says in TM 5-6675-371-12&P (Jan 09), a 5-year interval service is all you need.

When it's time for contractor service, get instructions from CECOM's Denise Ellis at DSN 848-2916, (443) 861-2916, or email:

denice.d.ellis.civ@mail.mil



Now AISI
needs
contractor
service once
every 5
years