

Connie's Post Scripts

M93 GPFU Configuration Changes

The M93 gas particulate filter unit (GPFU) has been modified. The M48A1 filter, NSN 4240-01-363-1311, is no longer part of the M93 and now must be ordered separately. The new M93 GPFU NSN without the M48A1 filter is NSN 4240-01-615-1867. By removing the M48A1, the M93's shelf life is extended.

Automotive Battery Handling PPE Change

The safety goggles, NSN 4240-00-269-7912, that are listed as Item 10 in WP 0034-2 of TM 9-6140-200-13 have been replaced with NSN 4240-01-460-1841. These replacement personal protective equipment (PPE) goggles fit over most prescription glasses so you can see and stay safe while pulling maintenance. Make this change to the PPE listed in your unit's battery TMs.

STRETCHY STRAPS FOR TRUCK TIRE CHAINS

Even after tightening your vehicle's tire chains by hand to avoid gouging, they still might be a little too loose. Correct that by snugging down the tire chains with a stretchy strap. Choose what you need from these options:

Length (in inches)	Strength (in inches)	NSN 5340-
15	20-30	01-029-9084
21	26-42	01-231-6015
31	36-42	01-029-9085

Fire Extinguisher for 5kW Generator

The 5-kW generator's 5-lb fire extinguisher is listed as NSN 4210-00-361-6921 in the Additional Authorization List (AAL) of TM 9-6115-659-13&P (Jan 10). That's **wrong**. The correct NSN is 4210-01-361-6921. Make a note until the TM is updated.

Attention PBOs: Watch Unit Transfers

As brigade combat teams begin reorganizing, the following information is important for property book officers (PBOs) to remember. To do a proper unit transfer in PBUSE, you must be sure that all DODAACs/transactions are sterilized and/or closed. Hung up due-ins (due-ins that have no status at a supply support activity [SSA], but still show status in PBUSE) and open items in suspense files are major reasons why unit transfers fail. If you are not running transactions on blast with the SSA to update your box, then it will result in multiple versions of files. To ensure a clean unit transfer, follow the instructions in Section 7 of the PBUSE End User Manual:

https://pbuse.lee.army.mil/gcss/help/eum/pdf/Section_7.pdf

M1200 Armored Knight VVID

For a look at the M1200 Armored Knight's vehicle version identification document (VVID), go to: <https://www.us.army.mil/suite/page/453627>

The VVID is a white paper that lists requirements for the M1200's equipment configuration. It serves as a hardware/software management tool that tracks upgrades, updates, problems and solutions for the Armored Knight and its line-replaceable units. You'll need an AKO account to view or download the VVID. Questions? Contact TACOM's Dave Merglewski at DSN 786-2299, (586) 282-2299, or by email at: david.merglewski.civ@mail.mil

Barber Kit NSN

What do you do if you need a haircut but you're stationed in a remote area far from a barber shop? You and your buddies will have to do your own barbering. So, get a barber kit, NSN 3590-00-058-1837. The kit includes manual and electric hair clippers, barber cloths, shaving cream, disposable safety razors, a disinfecting tray and other items to keep you well groomed.

M7 FRS Air Filter NSNs

Need a new air filter for the Cummins engine in your M7 forward repair system (FRS)? The filter for the Tier II engine (no turbocharger) comes with NSN 2940-01-619-2451. The filter for the Tier III engine (with turbocharger) is NSN 4130-01-559-5331. They replace NSN 2940-01-470-9846, shown as Item 12 in Fig 35 of TM 9-4940-568-24P (Feb 08), which brings the wrong air filter.

CRYPTOGRAPHIC EQUIPMENT WEBSITE

Need information on cryptographic devices? Go to the U.S. Army Cryptographic Modernization Device Portfolio website: <https://cryptomod.kc.us.army.mil/cryptomod.nsf>

The website hosts announcements, device wikis, downloads and solutions, training, a document library, FAQs/lessons learned and user forums. This is the only website where Army users can download cryptographic device software updates. A CAC card is required.

HUSKY Power Steering Filter

Get a new power steering filter for your MK III VMMD HUSKY with NSN 4330-01-605-4309. Make a note until the NSN is added as Item 19 in Fig 105 of TM 9-2355-316-23P.

M10A Forklift Brake Assembly

Get a new brake assembly for the M10A forklift with NSN 2530-01-195-0416. This NSN replaces PN 419-259, which is shown as Item 1 in Fig 115 of TM 10-3930-643-24P (Jul 93).

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?