


M1074A1,
M1075A1 PLS...

GET REPLACEMENT FOR SHIFT CABLE BOOT

THE BOOT ON MY
TRANSFER CASE SHIFT CABLE
HAS SPLIT OPEN. CAN YOU
ORDER ME A NEW ONE?

EVEN BETTER.
I CAN GET YOU
ONE FOR FREE!



Mechanics, the rubber boot, NSN 2530-01-192-4315, that covers the transfer case shift cable on the M1074A1 and M1075A1 PLS is deteriorating before it should.


As it weakens, the boot splits open between its folds. That allows dirt, debris and water to jam and corrode the shift cable.

If your truck is under warranty, go through the warranty process to get a replacement boot.

Out of warranty? No problem.

Just send an email to Oshkosh at:

[defensecampaigns@
defense.oshkoshcorp.com](mailto:defensecampaigns@defense.oshkoshcorp.com)



In the email, include a good shipping address. They'll send you a free replacement boot along with installation instructions.