


WATCH FOR BATTERY TRAY RETAINER CORROSION




Believe it or not, all battery retainers are not the same. That's especially true for the retainers used on battery trays for some FMTVs.

Turns out some of the battery retainers, NSN 6160-01-567-2595, did not receive a special coating before they left the factory floor. The coating is designed to help prevent corrosion.

Rather than replace them, Oshkosh has extended the warranty for battery trays with non-coated retainers to five years from the date of handoff. Battery trays with coated retainers still have a two-year warranty.

How do you know which retainers you have? The battery trays with non-coated retainers are tan. Trays with coated retainers are black.



If you have corrosion issues with coated or non-coated retainers that are still under warranty, call the Oshkosh warranty hotline at (800) 393-9921. Or send an email to:

warrantyclaims@defense.oshkoshcorp.com