



# ENGINE STARTER COULD BE A STOPPER!




**M**echanics, if you need to install a new starter on the engine of a HYEX 230LCR excavator, wait a second.

There's only one starter listed in TM 5-3805-280-23P-1 (Jul 11). But there are actually two different starters available. Both are very distinct in shape and color, so as long as you know the NSNs, you should have no problems getting the right replacements.

NSN 2925-01-473-9544 is the one shown as Item 3 in Fig 100 of the TM. It comes in a black housing.

The other starter is NSN 2920-01-510-1834 and comes in a gray housing. Make a note until this starter is added to the TM.

Black starter, NSN 2925-01-473-9544



Gray starter, NSN 2920-01-510-1834

