


WHAT'S BIANNUAL MEAN?



THIS SAYS YOUR SHOCK ABSORBERS SHOULD BE REPLACED DURING BIANNUAL SERVICES.

DOES THAT MEAN EVERY OTHER YEAR OR EVERY SIX MONTHS?

EVERY OTHER YEAR IS WHAT IT SHOULD MEAN.



Dear Half-Mast,

Page 46 in PS 734 (Jan 14) said that the HIMARS shock absorbers should be replaced as part of the biannual services. "Biannual" can mean twice a year or every two years. Which is it?

CW2 D.A.



CHIEF, BECAUSE IT HAS TWO MEANINGS, "BIANNUAL" WAS A POOR CHOICE OF WORDS. THE TERM WE SHOULD HAVE USED IS "BIENNIAL." THE SHOCK ABSORBERS SHOULD BE REPLACED EVERY TWO YEARS. SORRY FOR THE CONFUSION.

Line Up for SATS Tool Layout

Dear Half-Mast,

When I try to use the drawer tool layout in the SATS TM, the tools don't line up with the layout. Is there a better drawer layout available that would simplify inventory?

SFC R.B.

YOU BET, SERGEANT! TACOM HAS MADE A DETAILED DRAWER LAYOUT THAT CAN MAKE TRACKING SATS TOOLS A SNAP.

GET A COPY OF THE LAYOUT BY CONTACTING TACOM'S LAURA BETTCHER AT DSN 786-0301, (586) 282-0301, OR EMAIL:

laura.m.bettcher.civ@mail.mil

