

HMMWV...


# Need Frag Armor or OGPK Parts?

IF YOUR HMMWV'S FRAG ARMOR OR OBJECTIVE GUNNER PROTECTION KIT (OGPK) NEEDS REPAIR PARTS, DOWNLOAD TM 9-2540-239-13&P FROM THE ETM WEBSITE:

<https://www.logsa.army.mil/etms>

**RIGHT!** THE TM HAS OPERATOR INSTRUCTIONS, MAINTENANCE INFO AND REPAIR PARTS FOR THE FRAG ARMOR USED ON THE M1114, M1151A1/A2, M1165A1 AND M1167 VEHICLES...

...AS WELL AS THE OGPK USED ON THE M1114 OR M1151A1.




M1074, M1075 PLS...

# Got a Need for Speed Sensor?

I NEED A DIFFERENT SPEED SENSOR NOW THAT MY TRANSMISSION HAS BEEN **UPGRADED**.

AND HERE'S HOW TO GET IT!



**W**hen the M1074 and M1075 PLS trucks switched over to the new Allison 4500SP transmission, the vehicle's speed sensor had to be updated to handle a 24V system.

But when you check out Item 2 in Fig 1 of TM 9-2320-364-14&P in IETM EM 0206 (Apr 09), you'll notice there isn't an NSN listed. And PN 1857380U doesn't cross to an NSN.

Until an NSN is available, order the speed sensor directly from Oshkosh. Call 1-800-392-9921 or email: [partssales@defense.oshkoshcorp.com](mailto:partssales@defense.oshkoshcorp.com)