

★ Connie's Post Scripts ★

M939/A1/A2-Series Starters

Get the starter assembly for your M939- and M939A1-series trucks with NSN 2920-01-069-6997. It replaces NSN 2920-00-304-3493, which is listed as Item 2 in Fig 127 of TM 9-2320-272-24P-1 (Feb 99). The starter for the M939A2-series truck comes with NSN 2920-01-515-8434. It replaces NSN 2920-01-031-9027, which is listed as Item 1 in Fig 128 of the TM.

A1P2 LTAS FMTV Cab Door Damper

Get a new cab door damper for your A1P2 LTAS FMTVs with NSN 2510-01-627-6602. This is a universal damper that replaces NSNs 2510-01-575-4448 (A cab) and 2510-01-589-0359 (B cab armored kit). Those NSNs are currently shown as Item 24 in Fig 41 and Fig 1041 of TM 9-2320-333-14&P (IETM EM 0294, Jun 12).

BATTERY BOX COATING COMPOUND

If the interior coating on your vehicle's battery box is wearing out, you'll need to recoat it. Use a wire brush to scrape off rust and old paint. Then, after cleaning, protect the box by brushing on a coat of bituminous coating compound, NSN 8030-00-290-5141. That NSN brings one gallon of the compound.

621B SCRAPER STARTER NSN

Get a new starter for your 621B scraper with NSN 2920-01-443-7513. It replaces NSN 2920-01-123-8306, which is shown as Item 1 in Fig 50 of TM 5-3805-248-23P (Feb 06), and is a terminal item. You may notice the new starter is a bit smaller, but it serves the same fit, form and function as the old one.

GCSS-Army Reminder

Remember to check the GCSS-Army website for alerts, updated fielding and training schedules and other important info. Visit: <https://gcss.army.mil/>

Or sign up to get automatic notifications at: <https://gcss.army.mil/Support/register.aspx>

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 345239, requirements for the TB 43-PS-Series.

Would You Stake Your Life *right now* on
the Condition of Your Equipment?