

# MEL Changing for Some Components



**TB** 43-0002-11 (MAY 79) HAS LONG BEEN THE GO-TO MANUAL FOR MAINTENANCE EXPENDITURE LIMITS (MELS) ON GROUND SINGGARS COMPONENTS. HOWEVER, CECOM LCMC HAS NOW ISSUED AN **EXCEPTION**.

IN SUPPORT OF ONGOING MISSION READINESS, THE MEL FOR THE FOLLOWING COMPONENTS IS NOW AT 100 PERCENT OF REPLACEMENT COST:

Component	NSN
RT-1523E	5820-01-444-1219
RT-1523F	5820-01-535-3667
AM-7239E	5895-01-444-1218
AM-7238	5895-01-195-4844
AM-7238A	5895-01-306-8093
AM-7238B	5895-01-407-2627

**QUESTIONS?**  
CONTACT CECOM'S DAVID  
YANOSIK AT DSN 648-6232,  
(443) 395-6232, OR BY EMAIL:  
[david.w.yanosik.civ@mail.mil](mailto:david.w.yanosik.civ@mail.mil)

ALL OTHER COMPONENTS WILL KEEP THE MEL PERCENTAGE AS LISTED IN TB 43-0002-11. THAT INCLUDES **THESE** COMPONENTS...

Component	NSN
RT-1523	5820-01-234-8093
RT-1523A	5820-01-318-7990
RT-1523B	5820-01-365-2725
RT-1523C	5820-01-363-6929
RT-1523D	5820-01-410-8981
AM-7239	5895-01-188-8819
AM-7239A	5895-01-304-8389
AM-7239B	5895-01-334-3164
AM-7239C	5895-01-421-0093
AM-7239D	5895-01-422-8781