


FMTV...



YOUR NEW INTERCONNECTING BOX FINALLY CAME IN! I'D BETTER GET IT INSTALLED.

IF THAT'S THE ONE LISTED IN THE TM, YOU'LL HAVE TO SEND IT BACK. IT ONLY WORKS WITH MRAPS!




NAH! THIS IS THE **FREE ONE!** I THINK YOU'LL BE VERY HAPPY WITH IT.



INTERCONNECTING BOX OFFERED FOR **FREE!**



A NEW INTERCONNECTING BOX COMES WITH NSN 5895-01-591-7887. HOWEVER, ANY REQUISITIONS MAY BE PUT ON BACK ORDER UNTIL ENOUGH BOXES ARE AVAILABLE.



THE IETM INCORRECTLY LISTS NSN 5895-01-528-1514 FOR THE INTERCONNECTING BOX. BUT THAT BOX CONTAINS SOFTWARE THAT ONLY WORKS WITH **MRAP** VEHICLES.

AND THERE'S A POTENTIAL BONUS!

IF YOUR FMTV'S SERIAL NUMBER IS 100,001 OR ABOVE, YOU CAN GET A REPLACEMENT INTERCONNECTING BOX FOR **FREE**, MINUS THE COST OF SHIPPING, BY SENDING AN EMAIL TO: christophergrasso@dyn-intl.com

MAKE SURE YOU INCLUDE YOUR TRANSPORTATION ACCOUNT CODE (TAC), QUANTITY NEEDED, REQUIRED DELIVERY DATE, AND A GOOD SHIPPING ADDRESS THAT INCLUDES YOUR DODAAC, POC AND PHONE NUMBER.

IF YOU HAVE ANY QUESTIONS, CALL DYNACORP INTERNATIONAL'S CHRISTOPHER GRASSO AT (254) 288-4393.



THE FREE INTERCONNECTING BOXES ARE COMING FROM OLDER TRUCKS, SO STOCK IS VERY LIMITED. JUST MAKE SURE THAT YOU **CANCEL** ANY REQUISITIONS YOU MAY HAVE MADE FOR EITHER THE INCORRECT BOX, NSN 5895-01-528-1514, OR THE CORRECT BOX, NSN 5895-01-591-7887, BEFORE REQUESTING THE FREE INTERCONNECTING BOX.

IF YOU NEED HELP, CONTACT TACOM'S PAUL KAMINSKI, DSN 786-4328, (566) 282-4328, OR EMAIL paul.r.kaminski.civ@mail.mil