

MAKE AIR DRYER GOOD AS NEW!




SERVICING THE AIR DRYER ON BIG TRUCKS DOESN'T MEAN YOUR UNIT HAS TO FORK OVER LOTS OF MOOLA.



INSTEAD, TRY CLEANING THE DRYER BY USING A DESICCANT PARTS KIT. NSN 4440-01-081-1391.

THE KIT HAS EVERYTHING YOU NEED, INCLUDING INSTRUCTIONS, TO MAKE THE AIR DRYER AS GOOD AS NEW.



M113 FOV Oil Filter Replacement

When ordering a new oil filter for the M113 FOV's 6V53 engine, always use NSN 2940-01-633-3432 (PN PH3612). It replaces NSN 2940-01-197-7106 (PN FL804FP) which is shown as Item 9 in Fig 22 of TM 9-2815-205-24P. The old oil filter has a high rate of failure. Make a note until the TM is updated.

HMMWV Battery Type Revisited

Page 11 of PS 749 (Apr 15) indicated that the Exide 6TAGM (absorbed glass mat) battery, NSN 6140-01-485-1472, isn't authorized for use in HMMWVs. While that's true, it lead to some confusion about whether the Hawker 6TAGM battery, which comes with the same NSN, is allowed. Here's the straight scoop: Neither the Exide or Hawker 6TAGM is approved for use in the HMMWV. The only authorized HMMWV battery is the one called for in your TMs: the 6TMF, NSN 6140-01-446-9498.

Turn In Unserviceable MLRS PTOs

Have an unserviceable power take off (PTO), NSN 2520-01-463-5441, for your MLRS carrier? Turn it in immediately through the supply system. You'll improve combat readiness and earn an \$18,442 unserviceable credit.

IMPROVED MINI THERMAL MONOCULAR AVAILABLE

If your unit uses the Urban Operations Squad Set, NSN 5180-01-563-6719, an improved mini thermal monocular (MTM) is now available. The MTM-Product Improved (MTM-PI) is an upgrade to the set's current MTM. Its thermal viewer/camera has better range capability, resolution, and photo and video capture. The images the MTM-PI records can be downloaded to a CD/DVD for later use. It's designed to be hand-held, but it can also be mounted on a helmet or tripod. Order the MTM-PI with NSN 5855-01-590-9103. Questions? Contact Dan Stark at (586) 239-3678 or email: daniel.g.stark.civ@mail.mil

D7R II Tractor Fuel Injector Misfire

If the fuel injectors on your D7R dozer misfire, don't touch or try to repair them yourself. Instead, look at the serial number on the data plate. If it falls between KNA00214-00217 and KNA00219-781, contact your local Caterpillar dealer to schedule a repair and tell them it's regarding CAT Service Letter #PS44681. Travel and mileage are included, so there's no cost for the visit. Find your closest dealer at: <http://www.cat.com/dealer-locator>

GCCS-Army Reminder

Remember to check the GCCS-Army website for alerts, updated fielding and training schedules and other important info. Visit: <https://gccs.army.mil/> Or sign up to get automatic notifications at: <https://gccs.army.mil/Support/register.aspx>

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for the TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?