

# NEED PARTS FOR YOUR RADIO?



EVERYTHING'S CHECKING OUT HERE.

WE'RE ON A ROLL THEN. EVERYTHING'S GOOD HERE, TOO.

YOU GUYS ARE LUCKY! NOTHING SEEMS TO BE CHECKING OUT ON THIS RADIO. MAYBE SERGEANT BLADE CAN HELP ME OUT ON PARTS.


IF YOU HAVE QUESTIONS ABOUT THE RADIO SET, CONTACT CECOM'S MAN BLU LAU AT DSN 648-6415, (443) 395-6415, FAX (443) 395-6459 OR BY EMAIL: [man.b.lau.civ@mail.mil](mailto:man.b.lau.civ@mail.mil)

YOU CAN ALSO CONTACT ALENA SMITH-MARTIN AT 443-395-6235 OR BY EMAIL: [alena.m.smith-martin.civ@mail.mil](mailto:alena.m.smith-martin.civ@mail.mil)  
FOR MORE RADIO INFO, VISIT THE CSEL WEBSITE: <https://csel.army.mil/csel/menu.cfm>



Aircraft General...

## Army Does Test Set Calibration



IF YOUR COMPUTER TEST SET NEEDS CALIBRATION, TURN IT IN TO YOUR LOCAL TMDE SUPPORT CENTER.

DO NOT SHIP THE SET TO THE MANUFACTURER FOR CALIBRATION. IT'S NOT AUTHORIZED.

Dear Sergeant Blade,  
In my Army National Guard unit, I support the AN/PRQ-7 radio set, NSN 5820-01-499-4473. We're having trouble finding NSNs for the microphone boots and the battery release catch. Can you help us out with NSNs for these and any other parts?  
CW3 T.W.K

CAN DO! HERE'S A LIST OF ALL AVAILABLE SPARE PARTS TO GET THE AN/PRQ-7 OPERATIONAL...



There is no NSN for the safety latch. If you can't properly secure the battery, get a replacement radio like it says in Table 4-2 of TM 11-5820-1159-13.

Item	NSN
Cover replacement kit (microphone boots)	5895-01-587-8342
Non-rechargeable battery	6135-01-568-3234
Rechargeable battery	6140-01-534-3856
Antenna blade	5985-01-502-7930
Strap/pouch	5935-01-458-9450
Earphone	5995-01-502-9465
Earphone tips	5965-01-504-1051
Earphone cushions	5965-01-504-0072
Speaker cover kit	5895-01-587-8342
Antenna nut cap kit	5895-01-587-8349
Antenna rivet kit	5895-01-587-8346

On Page 60 of PS 742 (Sep 14), we told you to ship the TS-3920C/ASM computer test set (CTS), NSN 6625-01-529-3346, to the manufacturer for calibration. That's not the case.

The TMDE headshed says the TS-3920C/ASM is a secondary transfer level calibration according to TB 43-180, *Calibration and Repair Requirements for the Maintenance of Army Material*. That means factory calibration isn't authorized when the Army calibration program can handle the work. If you use the TS-3920C/ASM test set, turn it in to your local TMDE Support Center when it's time for calibration. They'll calibrate the test set using TB 9-6625-3617-24, *Calibration Procedure for Stabilization System Test Set Ultrax, Model TS3920C/ASM*.

Questions? Contact the TMDE POC, Gary Davenport, at DSN 645-8082, (256) 955-8082 or email: [gary.m.davenport.civ@mail.mil](mailto:gary.m.davenport.civ@mail.mil)