



Connie's POST SCRIPTS



HEMTT A4 Universal Service Kits

If you've ordered the HEMTT A4's universal annual service kit, NSN 4910-01-619-4329, in the past several months, you may have noticed a few items missing. Get those missing parts by calling Oshkosh's Alyssa Raymond at (920) 235-9151, extension 25519. She'll send you a Delta kit that includes the missing gasket (PN 9HR358) and two O-rings (PNs 19KP363 and 9HR356). The deadline for requesting the Delta kit is 16 Dec 15.

HEMTT A4 Universal Service Kit

The new HEMTT A4 universal service kit now comes with NSN 4910-01-619-4329. But if you have the M985A4 HEMTT guided missile transporter (GMT), you'll also need two additional kits for annual services: NSNs 4910-01-619-4329 and 4910-01-619-4330.

The Scoop on HMMWV Batteries

Page 11 of PS 749 (Apr 15) and Page 61 of PS 753 (Aug 15) said the only battery authorized for the HMMWV is the 6TMF, NSN 6140-01-446-9498. That battery is safe and what your TMs say to use. However, if your vehicle is already using the 6TAGM (absorbed glass mat) Hawker or Exide battery, NSN 6140-01-485-1472, don't change them out just yet. TACOM is testing the Hawker and Exide batteries to determine if they cause any problems with the HMMWV's electrical system. Until the results are in, continue using Hawker and Exide 6TAGM batteries that are already installed in your HMMWV.

M871A3 Semitrailer Clearance Light

Get the amber clearance light, including the base, for your M871A3 semitrailer with NSN 6220-01-595-4730 (PN 4337A). NSN 6220-01-499-3374 (PN M165A-MV), which is shown as Item 2 in Fig 2 of TM 9-2330-326-14&P (Feb 06), brings the LED light without the base. Make a note until the TM is changed at the next update.

CH-47F CARC Paint Touch-up Kits

After performing a modification work order (MWO) on your CH-47F, it's often necessary to do a little touch-up work to the aircraft's paint. Woodland desert sage (Fed std 34201, MIL-DTL-64159) CARC is available as a two-component kit (Type II) or as a self-contained portable touch-up kit (Type III):

Type	Size	NSN 8010-
II	3-qt kit	01-580-7175
III	30-ml cartridge	01-596-7845
III	450-ml cartridge	01-596-7861
III	900-ml cartridge	01-596-7853

M1101/M1102 SHOCK ABSORBER KIT

A shock absorber kit for the M1101 and M1102 trailers comes with NSN 2510-01-554-1785. The kit includes two shock absorbers and four locknuts for installation. The kit replaces NSN 2510-01-190-3862, which is shown as Item 6 in Fig 14 of TM 9-2330-392-13&P (Dec 12). That NSN is a terminal item.

A1P2 FMTV ELECTROMAGNETIC RELAY NSN

Get a new electromagnetic relay for your A1P2 model FMTV with NSN 6110-01-428-8915. It replaces NSN 5945-01-570-7989, shown as Item 18 in Fig 118 of TM 9-2320-333-14&P (Jun 12). The old NSN is a terminal item.

NEW LASER RANGE FINDER MAY HAVE WRONG MANUAL

Some units who received the new Model 1600 laser range finder (LRF), NSN 1240-01-620-2111, may have gotten the commercial manual for the old Model 1500, NSN 1240-01-562-9459. If that's happened to you, it's OK to keep using the Model 1600. Just remember the standard warnings about using a laser. If you didn't get the correct manual, contact Veronica Cook at DSN 786-1263, (586) 282-1263, or email: veronica.l.cook4.civ@mail.mil or Matt Williams at DSN 786-1274, (586) 282-1274, or email: matthew.w.williams21.civ@mail.mil

Turn In MLRS Unserviceable IEDBs

Have an unserviceable improved electronic distribution box (IEDB), NSN 6110-01-463-3913, for your MLRS carrier? Improve combat readiness and earn a \$21,660 unserviceable credit by turning it in immediately.

GCSS-Army Reminder

Remember to check the GCSS-Army website for alerts, updated fielding and training schedules and other important info. Visit: <https://gcss.army.mil/> Or sign up to get automatic notifications at: <https://gcss.army.mil/Support/register.aspx>

PARTS CLEANING CAN

Get a bench-type safety can with NSN 4940-00-684-0580. It's good for cleaning small parts. The can stands 6³/₄ inches tall and 11³/₄ inches wide. It holds up to two gallons of cleaning solvent and comes with side handles and a hinged lid. Appendix A of CTA 50-970 is your ordering authority.

BHL Alternator Impeller Fan NSN

Get a new alternator impeller fan for your backhoe loader (BHL) with NSN 4140-01-562-3619. It replaces NSN 2930-01-549-3106, which is shown as Item 5 in Fig 39 of TM 5-2420-231-24P (Jul 13). That NSN gets the wrong part.

MLRS Rearview Mirror NSN

Get a rearview mirror for your MLRS with NSN 2540-01-612-5318. It replaces NSN 2540-01-114-7652, which is shown as Item 11 in Fig 155 of TM 9-1450-646-24P (Jul 07).

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for the TB 43-PS-Series.

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?