

Bradley Fuel Cap Repair Kit

Use NSN 2590-01-461-5874 to order the new fuel cap repair kit for your M2/M3-series Bradley. The new kit will also be added to the PMCS annual power pack service kit, NSN 4910-01-461-2809. Make a note until the TMs are updated.

M1-Series Tank Screwdriver

NSN 5120-00-278-1283 gets a new flat-tip screwdriver, $\frac{5}{16}$ inch wide by 4 inches long, for your tank. It replaces NSN 5120-00-517-6906, which is listed in Appendix B of the -10-2 TMs and is no longer available. Make a note until the TMs are updated.

M1-Series Tank Bore Brush

Is the bristle section worn out on your tank's bore brush, NSN 1015-01-209-3483? Don't replace the whole brush. Get the bristle portion with NSN 1015-01-355-9526. Make a note until the NSN is added to the TMs.

M578 Tool Bracket

Use NSN 2540-00-409-8891 to order a new pioneer tool bracket assembly for your M578 recovery vehicle. The NSN listed for Item 20 in Fig 83 of TM 9-2350-238-24P-2 is obsolete.

