

## Wheel Lift Parts Available

**W**hen you need repair parts for your motor pool's wheel lift truck, NSN 4910-00-554-5983, don't look for NSNs. There are none.

You can get parts, though, by writing to:

**Nestor Sales Inc**  
7337 Bryan Dairy Rd  
Largo, FL 33777

Or you can call them at (727) 544-6114. Ext 376 gets the repair department and Ext 347 gets government sales.

THESE TIPS  
SHOULD GIVE  
YOU A LIFT!



## Truck MWO Generates Tires

**A**n on-going MWO to add antilock brakes to M939-series 5-ton trucks is generating serviceable tires that your unit might be able to use. The MWO puts new radial tires on basic model 939s, which means bias tires—NSN 2610-00-262-8653, 11.00-20, 12-ply, load range F—are excess to these trucks. If you have vehicles that use this tire, check with your local DRMO or MWO coordinator for what may be available in the system and how to get them.

## Ask the Tire Team

**H**ave questions about the tires used on your vehicles, or questions about tire safety, or about tire-related NSNs? Call the experts—TACOM's Team Tire—at DSN 786-4258/4271 or (810) 574-4258/4271. Or e-mail them at:

[teamtire@tacom.army.mil](mailto:teamtire@tacom.army.mil)

Visit their web site at:

<http://www.tacom.army.mil/immc/Support/Teamtire/home1.htm>