



Drip Pan and Pad

Need a new pan to catch oily drips from the drain plugs on your combat vehicle? Try NSN 4910-01-211-2195. It measures 36x24x1 1/2 inches. For extra protection against accidental spills, line the drip pan with an absorbent pad. NSN 4235-01-423-1463 gets four 32x17-in pads that absorb oil, but not water.

Longer CVC Cord

Need a longer cord to reach from the AN/VIC-1 intercom junction box to your CVC helmet? Take your choice. DH-132 helmets with the MK-1039/G headset-microphone use the CX-10767/GR 35-ft retractable cord, NSN 5995-00-434-5755. DH-132A helmets with the MK-1697/G headset-microphone take the CX-13037 23-ft retractable cord, NSN 5995-01-136-5973. Appendix A of CTA 50-970 is your authority for ordering.

Volcano OK on FMTV

Change 6 (Sep 00) to the M139 mine dispenser's TM 9-1095-208-10-1 has the mounting instructions to put the Volcano on the FMTV's 5-ton wrecker. Mounting instructions are on Pages 2-110.25 through 2-110.35 in -10-1.

Fire Extinguisher, Bracket

If you need the 5-lb dry chemical fire extinguisher, its bracket or both for your M809 and M939-series 5-ton truck, here's the information:

Extinguisher only:

NSN 4210-01-189-6452

Bracket only:

NSN 4210-01-183-4822

Extinguisher and bracket only:

NSN 4210-01-149-1356

Extinguisher, bracket and hardware:

NSN 4210-01-220-6376

M939 Defroster Assembly

NSN 2540-01-468-1852 gets the defroster assembly for M939/A1/A2-series trucks. The NSN is missing from Item 22 in Fig 551 of TM 9-2320-272-24P-2.

M35A3 CTIS Air Dryer Heater

To get a replacement 24-volt CTIS air dryer heater for the M35A3 truck, order modification kit, NSN 2530-01-465-3170. It contains the heater (28-volt), exhaust shield, lubricant and installation instructions. The heater is not available as a separate item.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life *right now* on the Condition of Your Equipment?