



YOU DON'T NEED  
A 6 1/2 SENSE TO  
DO THE RIGHT  
THING!

### Sheridan Seatbelts

Don't spend \$980 to order a new seatbelt assembly for your M551-series Sheridan when all you need is a \$40 lapbelt, NSN 1680-01-457-6960. Make a note until the NSN is added to Fig 130 of TM 9-2350-230-24P-1.

### CUCV Still Reportable

CUCVs will be in the supply system for the next 9 years as reportable items. When supply system parts run out, cannibalization and the commercial market will be your only parts sources. But check TB 43-0002-81 for the Maintenance Expenditure Limits, because CUCVs 11 years old and older have dropped off the list.

### STE-M1/FVS Adapter

Use NSN 4730-00-187-0840 to order the straight pin adapter for your STE- M1/FVS test set. The adapter, NSN 4730- 01-112-2286, shown for Item 25 in Fig F16 of TM 9-4910-751-14&P, is obsolete.

### Asset Visibility Training

The AMC Logistics Support Activity (LOGSA) is offering computer-based training on asset visibility reporting through the Internet and on CD-ROM. The course covers reporting procedures, regulations, automated tools and products, and troubleshooting. You can find the course at the LOGSA home page, <http://www.logsa.army.mil>, or write for the CD-ROM at:

LOGSA

ATTN: AMXLS-MS

Redstone Arsenal, AL 35898-7466

Questions? Call (256) 313-2488/2473, DSN 897-2488/2473

### M915 Truck Web Page

Info on the training, operation, maintenance and fielding of M915-series trucks can be found on the M915 Family of Vehicles web page: <http://www.acala1.ria.army.mil/DLCM/dsa/LCA/AF/M915>

### M1A2 Commander's Control

Need a new commander's control handle assembly for your M1A2 tank? Order NSN 1290-01-466-7722. Item 6 in Fig 31 of TM 9-2350-288-24P-2 is an older configuration that is no longer available.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

**Would You Stake Your Life *right now* on the Condition of Your Equipment?**