


# Detect This Help



WE'VE COME UP WITH A COUPLE OF SUGGESTIONS AT THE **ARMY ENGINEER SCHOOL** THAT'LL HELP SOLDIERS USE AND MAINTAIN THE AN/PSS-12 MINE DETECTOR...

✱ When you adjust the detector's sensitivity, you're supposed to hold the head 2 feet off the ground and away from any metal that could interfere with the reading. It's hard to hold the head like that while making the adjustment, so we drop to one knee and brace the detector handle on the other knee.

That gives you the right height and makes it easier to hold the head in that position.



✱ When you're assembling the mine detector, plug the covers on the cable and earphone connectors into the covers for the electronics unit. That keeps the covers from disappearing and also keeps the covers from filling with dirt and sand that can find their way to the connectors.



SGT Mark Mitchell  
USA Engineer School  
Ft Leonard Wood, MO

