

POST SCRIPTS

**PS 588
NOV 01**

Preserve Semitrailer Decking

Constant exposure to the elements dries, cracks and splinters the wood decking on semitrailers. Prevent that damage by spreading boiled linseed oil on the decking as needed. NSN 8010-00-152-3245 brings 1 gallon.

WANT TO GET PS EACH MONTH?

If so, have your pubs clerk go to <http://www.usapa.army.mil>. Once there, select **Publications Ordering**, then select **Subscription System and On-Line Reports**. After you log in, select menu option **USAPA On-Line Ordering**. Click on **SEARCH** and search by IDN 340312. Check the **Subscribe** box for the first entry of TB-43-PS-xxx, enter the number of PSs you want, hit **ADD TO SELECTION**, then hit **Submit Selections**. You're done. PS will be mailed to you monthly.

New Web Site for MWOs

The Modification Management Information System (MMIS) web site for MWOs has changed its Internet address. Go to <http://65.196.121.253/mwo> and you will be back in business. Questions about the MMIS system go to Bob Lane, MMIS Contractor, at (703) 998-1941. Questions about MWOs go to Grover Gibson, HQ AMC, at DSN 767-0856 or (703) 617-0856.

STATEMENT OF OWNERSHIP, MANAGEMENT AND CIRCULATION

Title of Publication:
PS, The Preventive Maintenance Monthly
Publication No. 341-950
Date of Filing: 26 Sept 01
Frequency of Issue: Monthly
No. of Issues Published Annually: 12
Annual Subscription Price:
Domestic \$30.00 Foreign \$37.50
Complete Mailing Address of Publication:
USAMC Logistics Support Activity, PS Magazine
5307 Sparkman Circle, AMXLS-LP
Redstone Arsenal, AL 35898-5000
Complete Mailing Address of Headquarters or
General Business Office of Publisher:
Department of the Army
The Pentagon
Washington, DC 20310
Publisher: Department of the Army
Editor: Jerome J. Hill
Managing Editor: Ray G. Hanson

Known Bondholders, Mortgagees, and Other Security Holders Owning or Holding 1 Percent or More of Total Amount of Bonds, Mortgages, or other Securities: **None**
Tax Status: The purpose, function, and nonprofit status of this organization and the exempt status for federal income tax purposes has not changed during the preceding 12 months

Extent and Nature of Circulation	Last year	Last issue
a. Total # Copies	97,174	96,812
b.(1) subscriptions	90,531	90,319
b.(3) non-USPS	4,758	4,743
c. Circulation	95,289	95,062
d. Free Distrib/mail	716	716
e. Other free	180	180
f. Total Free	896	896
g. Total Distribution	96,185	95,958
h.(1) Office Use	989	854
i. Total	97,174	96,812
Percent Req'd	99.07%	99.07%

Submitted by: W. Richard Morris, Production Manager

CONSTRUCTION EQUIPMENT WEB SITE

Need info on maintenance, parts or Tank-automotive and Armaments Command (TACOM) points of contact for construction equipment? Take a look at the following web site: <http://www-acala1.ria.army.mil/LC/CJ/CJC/cegrouph.htm>

M915A1 WATER TEMP SWITCH

NSN 6685-01-081-9721 brings the M915A1 tractor truck's thermostatic water temperature switch. The NSN shown for Item 3 in Fig 42 of TM 9-2320-283-24P gets the wrong switch.

M109A6/M992A2 MANIFOLD STUD

Use NSN 5307-01-371-2402 to order a replacement stud for the exhaust manifold on your M109A6 Paladin and M992A2 ammo carrier's 8V71T LHR engine. The part number listed as Item 9 in Fig 27 of TM 9-2815-202-24P should be 23504822. Pencil in the right part number until the TM is updated.

External APU Starter

NSN 2920-01-467-7912 gets the new 24-volt starter for the external auxiliary power unit, NSN 6115-01-459-4514, on your M1-series tanks. The NSN shown as Item 1 in Fig 37 of TM 9-6115-542-24P is no longer available.

M109A6 PALADIN SEALANT

Use NSN 8040-00-152-0063 to get the adhesive listed as Item 7 in Appendix C of TM 9-2350-314-20-2-2. The listed part number and CAGE don't cross to an NSN on the FED LOG. Make a note until the TM is updated.

AVLB VISION BLOCK

NSN 6650-01-302-7685 gets the direct vision block for the AVLB using either the M48A5 or M60A1 tank chassis. The NSN shown for Item 5 in Fig 185 of TM 5-5420-226-24P and Item 20 in Fig 196 of TM 5-5420-202-24P is no longer good.



DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series

Would You Stake Your Life ^{right now} on the Condition of Your Equipment?