

TRACK M3P ROUNDS TO STAY ON TRACK



If you don't keep track of how many rounds your Avenger's M3P machine gun fires, you'll miss its 2,500-round inspection.

That means the M3P's extractor, sear slide, firing pin, and cocking lever may not be replaced when they're worn out. An M3P with worn parts fires poorly.

So record the rounds fired on a DA Form 2408-4, *Weapons Record Data*, every time you fire. All rounds—live and blank—count toward that 2,500 limit.

ATACMS...

SEAL OUT MOISTURE



That's why it's critical that you repairmen check the humidity indicator's gasket when you change the indicator. If the gasket is cracked, deformed, or doesn't seal properly, it won't be able to seal out moisture.

If the gasket is bad, replace it with NSN 5330-01-146-7182. You do not need to replace the entire sight glass just because of a bad gasket.

