

# HARD TO FIND REPAIR PARTS

**T**rying to find repair parts for the 3,000-GPH trailer-mounted ROWPU can be a real puzzler. That's because some old parts are no longer available or the parts info in the TM has changed.

Make a note of these changes in TM 10-4610-232-24P until there's a change or revision to the technical manual.

Item	Figure	NSN	Name
41	3	5340-01-468-4943	Plate, mounting
2	43	2540-01-468-5020	Latch, electrical panel door
96	67	5330-01-467-1605	Gasket, retainer in booster pump discharge assembly
13	69	4730-01-467-1526	Clamp, product water out
1	72	5340-01-468-4937	Clamp, basket retainer
4	80	4810-01-467-1589	Valve, solenoid assembly
4	81	4810-01-467-1591	Valve, solenoid assembly
17	83	5999-01-467-1685	Level switch
18	83	5999-01-467-1676	Level switch
19	83	5999-01-467-1683	Level switch
9	84	4730-01-467-1501	Clamp, multi-media tank
4	116	4730-01-468-5339	Elbow, waste out (AquaChem Models only)
33	BULK	5330-01-468-5373	Material, electrical panel seal

