


AN/PRC-112...

# PROBLEMS GET FIXED


**NEWSFLASH!  
...THIS JUST IN...  
FREE UPGRADES  
BEING GIVEN TO  
AN/PRC-112  
RADIOS!!**

**NOW THAT'S  
WHAT I NEED  
TO HEAR!**



1. The large VOL/OFF knob can accidentally be turned on when the radio is handled. If turned on and left on, it drains the battery.
2. Water seeps into the radio's case.
3. Frequency hopping happens by chance due to the design of the radio's transponder.

HERE'S HOW AN UPGRADE PROGRAM THAT'S UNDERWAY FOR THE AN/PRC-112 SOLVES **ALL THREE PROBLEMS...**



1. Current VOL/OFF knob is replaced with a smaller knob that is more difficult to accidentally turn on.

2. A new, better gasket that stops water intrusion is installed in the lid of the case.

3. A more efficient transponder is added that corrects chance frequency hopping.

It is important to find out if your radio has been upgraded.

If your radio's NSN is 5820-01-458-6018, then it has been upgraded.

If your radio's NSN is 5820-01-279-5450 and a Tobyhanna Army Depot (TYAD) sticker has been added, then the radio has been upgraded.

If the NSN is 5820-01-279-5450 and there is no TYAD sticker, then the radio needs to be upgraded.

Contact CECOM at DSN 992-1191 or (732) 532-1191 or e-mail at:

bruce.jetter@  
mail1.monmouth.army.mil  
for instructions on how to get the upgrade.