

Connie's ☆ POST ☆ SCRIPTS

DON'T WAIT
TIL HIGH
NOON TO
START YOUR
PM!

YOU SHOULD
BE DOING IT
ALL THE
TIME!



EOD MWO WRONG

MWO 9-2320-288-20-6 listed in the explosives ordnance disposal's TM 9-4940-566-23&P and the contact maintenance shop equipment's TM 9-4940-563-13&P is wrong. The correct number is MWO 9-2320-280-20-6. The MWO is listed on the Warning Summary page and in Para b on Page 0002 00-1 in TM 9-4940-566-23&P and on the Warning Summary Page C and in Para 1-7 b on Page 1-7 in TM 9-4940-563-13&P.

MKT Food Containers

Are you having trouble getting the latest insulated food containers (IFC) used on all MKTs? Order NSN 7360-01-419-8500.

INSULATED FOOD CONTAINER GASKETS

If you've got worn-out gaskets on your insulated food containers, NSN 7360-01-419-8500, order NSN 7360-01-456-9114 for the pan gasket, and NSN 7360-01-456-9113 for the lid gasket.

Defective GPFU Fans

Fans made for the M93 gas-particulate filter unit (GPFU) may be defective. It is critical that defective fans be identified and replaced because no fan means the GPFU provides no NBC protection. How to tell? Check the GPFU's identification plate. If your GPFU was made by Hunter Manufacturing, Keco Enterprises, or Donaldson Company, check the contract number. It will say DAAE20-XX, with the XX being the year of the contract, such as 98 for 1998. If your GPFU was contracted for in 1996 or later, contact SBCCOM's Guy Cabell at (309) 782-7126/DSN 793-7126 or cabellg@ria.army.mil. He will tell you if you have a defective fan and how to get a replacement. If your fan's contract year is before 1996, your fan is OK.

Use PATS, Not BANANA OIL

The M41 PATS is the most accurate way for an NBC NCO to test the fit and condition of an M40/M42-series mask. The old banana oil smell method does not even come close. Unfortunately, some NBC NCOs are still using banana oil to test masks for soldiers deploying overseas. Then when the soldier arrives overseas he's tested with PATS and his mask flunks the fit test. Not good! Use PATS, not banana oil, for testing masks.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on
the Condition of Your Equipment?