

HYEX...

**CRANK GNRRR**  
**CRANK GRIND**  
**CRANK GRIND**  
**GNRRR**  
**GRIND**  
**GNRRR**




## Rough Start Reminder

Operators, your hydraulic excavator may be hard to start when the temperature drops below freezing.

The cold weather starter system has a fuel canister that automatically injects ether into the engine when you push the cold start button.

If your excavator is hard to start even when using the cold start button, chances are the ether canister is empty. Have your mechanic replace it.

Replace canister when empty



815F Compactor...

## Sneaky Leak Fix

**M**echanics, a little tape takes care of a sneaky leak that can get on your nerves.

After cleaning out the crud in the compactor's fuel tank, you have to reinstall the tank's drain plug. Make it leak proof with antiseize tape, NSN 8030-00-889-3535.

When you do:

- Make sure the threads are free from dirt, fuel and oil.
- Wrap the tape in the direction of the plug's threads. Use two turns and overlap about half a wrap.

USE ANTISEIZE TAPE, NSN 8030-00-889-3535, ON THE DRAIN PLUG'S THREADS.

