



DIPSTICK COMES UP SHORT




You're going to have a hard time checking the engine oil level on your howitzer or ammo carrier with replacement dipstick, NSN 6680-00-257-1396. It's a little too short for the job.

You'll need to order dipstick, NSN 6680-01-503-4823, instead. That dipstick is a little long, so you'll need to modify it according to the engine model in your vehicle.

For models 7083-7391, 7083-7396, and 7083-7399, cut, bevel the edges and add markings like so:



For models 7083-7395 and 7083-7398, cut, bevel the edges and add markings like this:



MAKE A NOTE OF THE NEW DIPSTICK NSN AS *ITEM 2* IN THE BULK SECTION OF TM 9-2815-202-24P UNTIL THE TM CAN BE UPDATED.