


# OUT OF YOUR DEPTH



**W**hen taking your M1-series tank's mine clearing blade through brushy areas, the depth indicators take a beating. Sometimes the beating's bad enough to bend or even break the indicators.

A broken or missing indicator deadlines your mine blade. A bent one does not. But it still makes it hard to tell how deep you're plowing. When it comes to dealing with mines, you never want to be out of your depth!

There's no NSN for a replacement shaft. Instead, you'll have to order a complete depth indicator kit, NSN 2590-01-462-3313. The kit costs \$109, but includes 2 depth indicators and all the hardware needed for installation. Instructions for installing the kit are on Page 2-132 of TM 9-2590-509-23&P.

