


# Switch Selection SIGNIFICANT

HMM...  
SABOT,  
MPAT STAFF  
OR HEAT?


I WONDER  
WHAT'S THE  
*RIGHT* SETTING  
FOR MY M908  
ROUNDS?



**G**unners, selecting the right position on the GPS ammunition select switch isn't so clear-cut when it comes to using M908 high explosive obstacle reduction tracer rounds. The switch doesn't specifically pinpoint the right setting to use.

The correct setting is MPAT. Until the TMs can be updated, get out your stubby pencils and make the following change to the -10-1 TMs:

**(Note: When firing M908 ammunition, gunners must select MPAT on the ammunition select switch.)**



Add the note after Step C on Page 2-421 of TM 9-2350-264-10-1 (M1A1). The note goes after Step D on Page 2-598 of TM 9-2350-288-10-1 (M1A2) and Page 2-581 of TM 9-2350-388-10-1 (M1A2 SEP).

The complete scoop's in TACOM Maintenance Advisory Message 03-015. See your local TACOM LAR for a copy.

Select MPAT when firing M908 rounds