



## VIDEO AVAILABLE

There's a 20-minute video available on snow-plow operations for HMMWV drivers in cold weather. The video also shows how to install and use tire chains on the vehicle. You can get two free copies of the video just by asking. Write to:

Commander  
US Army Research and  
Development Center  
Cold Regions Research and  
Engineering Laboratory  
Attn: Librarian  
72 Lyme Road  
Hanover, NH 03755-1290

Make sure to include your name, unit and address when writing. Or e-mail:  
[Elizabeth.R.Hoffmeister@erdc.usace.army.mil](mailto:Elizabeth.R.Hoffmeister@erdc.usace.army.mil)

## M101/M116 Brake Strut

Use NSN 2530-01-074-7001 to get the left (road side) parking brake strut for the M101- and M116-series 3/4-ton trailers. The NSN is missing from Fig 8 of TM 9-2330-202-14&P.

## PROTECT BATTERY RECEPTACLES

Listen up! Nickel-cadmium battery receptacles need protection from corrosion and external shorts while in storage. Terminal covers used on generator batteries are OK to use. Order with NSN 5999-01-382-8223.

## FMTV Desert Tan Covers

The FMTV parts manuals come up short when it comes to the desert tan cargo cover with bows. Get the cover and bows for your 2 1/2-ton with NSN 2540-01-437-1463. NSN 2540-01-436-9658 gets the cover and bows for 5-tonners.

## M872/A1/A2 Semitrailer Axle

NSN 2530-01-197-2032 gets a non-driving axle assembly for the 34-ton flatbed semitrailer. The parts info shown as Item 1 in Fig 13 of TM 9-2330-359-14&P gets the wrong assembly.

## M871A2 Quick Release Pin

NSN 5315-01-507-4461 gets the new quick release pin for the side panel stakes on the 221/2-ton semitrailer. This NSN replaces the one shown as Item 8, Fig 30 of TM 9-2330-386-14&P.

## M1022 DOLLY SET AXLE SEAL

Use NSN 5330-01-082-7965 to get an axle grease seal ring for the M1022 dolly set. This NSN replaces the parts info shown for Item 18, Fig 12 of TM 9-2330-379-14&P.

## M915A3 HEADLIGHT SWITCH

NSN 5930-00-307-8856 gets the headlight switch for the tractor truck. The NSN is missing from Item 13, Fig 69, of TM 9-2320-302-24P.

## M915-Series Seat Belt

NSN 2540-00-894-1273 gets the seat belt for the M915-series tractor truck. This NSN replaces the parts info shown as Item 17, Fig 255, of TM 9-2320-273-24P.

## NO MO' CAMO

The Army is no longer ordering the lightweight camouflage screening system (LCSS), its parts or repair kits. If you have to repair your LCSS, use parts from old nets as long as possible. When your LCSS is beyond repair, order the ultralightweight camouflage net systems (ULCANS). You'll find the NSNs in TM 5-1080-250-12&P.

## GENERATOR BATTERY COVERS

Use battery terminal covers, NSN 5999-01-382-8223, on your generator batteries. They will give corrosion protection and keep metal to metal contact from happening.

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life *right now* on  
the Condition of Your Equipment?