

NO RED DOT? USE IT NOT!



Tankers, don't use the tank gun fire device simulator (Hoffman device), NSN 6920-01-067-1667, on your M1-series tank unless the simulator has been modified. An unmodified Hoffman device can create an electrical spike that could damage your tank's electrical system or even cause the M21 pyrotechnic charges to fire prematurely.

Modified simulators have a dime-sized red dot on the side. You'll also find a second, smaller red dot near the modified area of the MILES M1 kill indicator cable, NSN 6150-01-306-9431.

If your simulator or MILES cable doesn't have the markings, don't use them. Turn in the device to your Training Support Center or directly to DRMO using a Demil Code of D. That will ensure the device is destroyed and can't be used again.

Questions? Contact Conrad Ortega, PEOSTRI, at DSN 970-3766, (407) 384-3766, or send an email to:

conrad_ortega@peostri.army.mil

