



TGMD Fuse Holder NSN



Dear Editor,

We've had a problem getting the fuse holder, NSN 5920-00-926-7517, for the transmission group multiplexer/demultiplexer (TGMD) in our AN/TRC-190(V)3 line of sight (LOS) shelter.

The fuse holder has an acquisition advice code of "Y", which means further procurement is not authorized. We found a substitute that works. It's NSN 5920-00-740-0017.



SFC Steven Coleman
122d Sig Bn, Camp Casey, Korea

From the desk of the *Editor*

For our Marine readers, NSN 5920-00-740-0017 is coded "V", which means there is current stock but future procurement is not authorized. FED LOG tells Marines to use NSN 5920-00-926-7517 when supply is exhausted. But like the Army, that NSN is coded "Y" for Marines. An alternative NSN that is coded "D" is NSN 5920-00-887-6514. It works, but does not have a lamp on the fuse holder cap like the other fuse holders.