


DO YOU DO WINDOWS?



When the driver's vision enhancer (DVE), video display terminal (VDT), or remote weapons system (RWS) sights on your Stryker get dirty, **don't** use a shirt tail or a greasy rag to wipe them off.

Using whatever's handy to clean those items will lead to scratching. Eventually, the glass gets so bad that you have trouble seeing through it.

Your best bet is to use lens tissue, NSN 6640-00-285-4694, and lens cleaner, NSN 6850-00-227-1887, for cleaning.

