

**HEY,
YOU!**

**WHO,
ME?**

**NO OIL
PRESSURE
BURNS ME UP!**

**YEAH,
YOU!**

**DON'T FRY THE
TURBOCHARGER!
RUN YOUR STRYKER AT
LOW IDLE FOR 3 MINUTES
BEFORE SHUTDOWN!**