


# Solve a Mounting Problem




Chances are your howitzer, tank or personnel carrier has said goodbye to the AN/VIC-1(V) intercommunication set by now and said hello to the AN/VIC-3(V). If not, you might be in need of mounting hardware for the VIC-1 components.

For the audio-frequency amplifier, AM-1780C/VRC, NSN 5996-01-520-5679, you need mounting hardware, NSN 5340-00-254-6401.

The four intercommunication control sets each have their own hardware. None of the bags of hardware have NSNs, so they must be ordered by part number on a DD Form 1348-6.



HERE ARE THE SETS, THEIR NSNs AND THE PART NUMBERS FOR THEIR MOUNTING HARDWARE...



Sets	NSN	Hardware PN
C-2296	5820-00-892-3337	SM-B-415268
C-2297	5820-00-892-3338	SM-B-415252
C-2298	5820-00-892-3339	SM-B-415234
C-10456	5830-01-082-0804	SM-B-415269