



M88A1 Air Cleaner Parts

The numbers for Items 22 and 23 in Fig 21 of TM 9-2350-256-24P-1 are reversed. If you order Item 22, the rubber collar flange, you'll actually receive what's pictured as Item 23. And if you order Item 23, the air duct collar, you'll receive what's pictured as Item 22. Also, the CAGE and part number for Item 23 are both missing their first number. The correct CAGE is 19207. The part number is 10862222. Make a note until the TM can be updated.

No Training with Old M2 Barrel Support

We told you in PS 627 (Feb 05) that because of a shortage in M2 machine gun barrel supports it is temporarily OK to use the old barrel support with rectangular cooling holes. But because the old support has larger cooling holes it's *not* OK to use it for training with the M19 BFA, M3 recoil amplifier, or MILES. The old barrel supports should be tagged NOT FOR USE WITH M3 AMPLIFIER, MILES OR BFA and you should make sure you have the new barrel support, NSN 1005-00-550-4091, for training. Questions? Contact TACOM's Katie Asleson at DSN 793-3786/(309) 782-3786 or email: katie.asleson@us.army.mil

M1A1 Tank DSESTS Software

Have you had DSPS 32.1 software loaded on your Direct Support Electrical Systems Test Set (DSESTS) with a Combined Support Function Module (CSFM)? Without it, you won't be able to check the tank commander's panel (TCP), PN 12549797-3, on tanks that have had MWO 9-2350-264-50-12 applied. A faulty TCP won't alert the commander when the NBC system overheats or is clogged. Nor will it automatically shut down the NBC system to avoid a possible fire.

M1A1 Tank Commander's Panels

If you need a new tank commander's panel (TCP) for your M1A1 tank or an upgraded tank commander's panel (UTCP) for your M1A1 AIM tank, be sure you order the latest versions. Requisitions for the older, obsolete versions will be rejected. The new TCP is NSN 6110-01-497-3343 (PN 12549797-3). The new UTCP is NSN 1290-01-511-9539 (PN 12473169). Pencil in these NSNs until TM 9-2350-264-24P-2 can be changed.

AR 750-1 2005 Released

The 2003 version of AR 750-1, *Army Materiel Maintenance Policy*, was replaced on 15 Aug. The revision is available on the Army Publishing Directorate website:

http://www.army.mil/usapa/epubs/750_Series_Collection_1.html

DISTRIBUTION: To be distributed in accordance with the initial distribution number (IDN) 340312, requirements for TB 43-PS-Series.

Would You Stake Your Life ^{right now} on
the Condition of Your Equipment?