


Kicking the Habit



Drivers, your tanks have kicked the smoking habit!

So if you've been trying to use the smoke generator, give it up. All current M1-series tanks use JP8 fuel. And JP8 **won't** smoke!

Now that doesn't mean you should physically disconnect the smoke generator system. Nor should you put tape over the smoke generator switch. In fact, neither action is authorized by TACOM.

Why? Well, just because your tank uses JP8 today, doesn't mean the fuel won't be changed to something else in the future. And if that fuel allows smoking, you'll want the smoke generator system to be up-to-snuff.

So, keep the smoke generator mission-ready, but don't try to use it.

