

Making IETM Surfing Simple



Using the Stryker IETM can be a real pain when you need to go back and forth between a maintenance task and the repair parts listing.

Does this sound familiar? The maintenance task calls for a part. You go to the repair parts listing to find it. Then you have to go back to the maintenance table of contents, find the maintenance task again, and go to it.

There is an easier way. Saving time and effort when going back and forth between a maintenance task and repair part listing is as easy as 1, 2, 3:

1. At the maintenance task page, click on the blue link for the repair parts figure you need to access. It'll be located under the References heading at the top of the maintenance task. This link will take you to the repair parts listing.
2. When you've gathered the parts info you need and you're ready to return to the maintenance task, click on the Back button at the bottom left corner of the screen. This will take you to the main repair parts listing screen.
3. Click on the Back button located as the third option bar in the center of the page. This will take you back to the original maintenance task.

From repair parts listing, press Back button

To return to maintenance task, click on Back button