

FINDING PARTS TO REPAIR ARMOR, COOLING

FINDING THE *RIGHT*
PARTS FOR YOUR M1083
AND M1088 FMTVs IS
JUST A *CLICK* AWAY!



Dear Half-Mast,

Our unit has new up-armored M1083 and M1088 FMTVs. After eyeballing the electronic technical manuals (ETMs) on EM 0122, I didn't find a thing on the factory-installed air conditioner, not even a picture! I couldn't find parts for the armor components either.

How can we find the NSNs that we need?

SSG A.C.

Dear Sergeant A.C.,

You have two problems! The FMTV models you named are -A1 models, not basic models. You won't find what you need in EM 0122 because it covers the basic model FMTV. See EM 0195 for information on -A1 models—except for the armor and AC info!

The armor and air conditioning information is **only** available in TB 9-2320-320-13&P (Jul 05) for the low signature armor cab (LSAC) and TB 9-2320-316-14&P (Oct 05) for the cab add-on armor (AOA) kit.

You can access these technical bulletins online:

<https://www.logsa.army.mil/etms>

Half-Mast