

**SAVED FUEL
WILL COST YOU!**



Dear Editor,

I have seen soldiers and mechanics dumping the fuel from the old fuel filter into the *new* fuel filter. That's a no-go!

When they do this, they are also dumping some of the dirt into the new fuel filter. This can clog the new filter more quickly than necessary.

Help me get the word out so this can stop.

SFC
FMS #6A
Show Low, AZ

Editor's note: Thanks for the tip! They're probably doing this so they don't have to properly dispose of the fuel. A good rule to follow: If the TM doesn't tell ya' to do it, don't.

Wipers for M44A2, M809

Want an electric windshield wiper for your older 2¹/₂-ton and 5-ton trucks? Accessory kit, NSN 6105-01-461-7073, is available as a replacement for air-actuated units on M44A2-series 2¹/₂-ton trucks and M809-series 5-ton trucks. TACOM's EIR Digest, TB 43-0001-62-5 (Apr 00), approved this switch so that drivers—not the engine—determine how fast the wipers work. See your TACOM LAR for a copy of the EIR Digest info, or email

Half.mast@us.army.mil