


Get the Right Tire Chains



Tire chains can come in handy for your Stryker when winter weather arrives. But the chains were left out of some of the -10 TM additional authorized lists (AAL), while one other lists the wrong chain.

The correct NSN for Stryker tire chains is 2540-01-498-8821. This is a 0.8-mm chain that's made of high-grade material and fits the Stryker's tires perfectly.

Use proper
tire chains
on your
Stryker



UNTIL
THE NEXT
UPDATE,
ADD THIS
CHAIN TO THE
AAL OF THE
FOLLOWING
TMS...



- TM 9-2355-311-10-2, M1126 RV
- TM 9-2355-311-10-4, M1130 CV
- TM 9-2355-311-10-5, M1127 RSV
- TM 9-2355-311-10-6-2, M1132 ESV
- TM 9-2355-311-10-7, M1134 ATGM
- TM 9-2355-311-10-8, M1133 MEV
- TM 9-2355-311-10-9, M1131 FSV

TM 9-2355-311-10-3, the M1129E1 MC (B Variant) lists the wrong tire chain, NSN 2540-21-914-4252, in the AAL. This is a 0.5-mm chain that's actually made for the Marine Corps LAV. It won't fit properly on the Stryker and doesn't last very long, so scratch it out and replace it with NSN 2540-01-498-8821.