

M1126 ICV
Stryker...

Remember to Unlock the Lock

...AND
HERE'S MY
ESTIMATE.



HOLY
COW!!




ALL THIS
BECAUSE WE
FORGOT TO
DISENGAGE
THE AZIMUTH
TRAVEL LOCK
ON OUR RWS!?:




You don't expect to cause damage to your M1126 ICV Stryker during PMCS, but it can happen!

PMCS requires you to check the inhibit zones on the remote weapons system (RWS) followed by combat override to check full rotation. But, did you remember to disengage the azimuth travel lock first?

Before
rotating
RWS during
PMCS...



...remember
to unlock
azimuth
travel lock



If you didn't, the lock snaps and you have to replace the entire mainframe assembly, NSN 2510-25-150-7443, at a cost of nearly \$97,000!

So, write yourself a note, tie a string around your finger...whatever it takes. Just make sure you remember to unlock the azimuth lock!