


HMMWV...

# CAUGHT BETWEEN A ROCK AND A HARDTOP



Dear Half-Mast,

We've had several of our M998 HMMWVs outfitted with the new fiberglass hardtops. Problem is, we're having a hard time finding replacement parts as they wear out.

The HMMWV parts TM doesn't cover the hardtop and we haven't been able to find any other TMs that do either.

In particular, we've had several of the gas spring sets go out on the rear door and we need to get them replaced. Can you help us out?

SSG B.T.W.

Dear Sergeant B.T.W.,

Sure can! The fiberglass hardtop hasn't been provisioned for repair parts, so there are no NSNs. However, you can get the parts you need by going directly to the manufacturer.

The hardtop is manufactured by AMTECH Corporation. Their website is:

[http://www.amtechcorp.com/military/mp\\_home.php](http://www.amtechcorp.com/military/mp_home.php)

Once there, click on Accessories and then on Spare Parts (Click HERE). Click on the repair part you need for part number information. For example, the gas spring set for the rear door is PN 100953.

Once you've found the part you need, give AMTECH's Sarah Cassel a call at 1-800-537-0762 or send an email to [scassel@amtechcorp.com](mailto:scassel@amtechcorp.com) for help in ordering.

Half-Mast