


Pressure Refueling ERFS II Tanks



Crews, you can't afford to miss a beat when it comes to your Chinook extended range fuel system II (ERFS II).

When the ERFS II tanks are pressure refueled, make sure you follow the procedures like it says in Paras 2-248-2-249 of TM 1-1520-240-10. Place all the valves in their proper positions during and after refueling. After refueling is complete, your bird's main fuel tanks could overflow if the valves on the ERFS II tanks are not in their proper positions.

Make a note of the warning on page 2-110 and 2-111 before manually operating the fuel/defuel valve.

If you leave the valves in the wrong position, fuel spills will occur. That's a nightmare because a fuel spill is a messy cleanup.

