


Save Yourself Some Money

*DON'T
ORDER
THE FILTER
ASSEMBLY...*

*...JUST
GET THE
FILTER
ELEMENT!*



Mechanics, the Pall purifier, NSN 4330-01-522-2007, does a great job in purifying and purging your Chinook's hydraulic systems.

You'll be glad to hear you can save money when ordering parts. The commercial parts manual lists the coalescing filter assembly, NSN 4330-01-529-1901, as a filter. But it should be broken down to show there's a filter element available. That's good news.

Make a note that the coalescing filter assembly contains a filter element, NSN 4330-00-300-7749, that can be ordered.

If you've been ordering the complete assembly to replace the filter element, **STOP**. Just order the filter element. Stocks are on hand.

In fact, the coalescing filter assembly is not readily available in the supply system. Replacing the assembly costs a whopping \$639.00 while the filter element only cost \$127.00. That's a big saving to your unit's bottom line.

Pencil in the filter element NSN in your commercial manual until it is updated.