


SENDING IN PARTS FOR REPAIR



WHEN THESE AND OTHER PARTS OF THE FLIR FAIL, WHERE SHOULD YOU SEND THEM?



TOBYHANNA ARMY DEPOT— THAT'S WHERE!

TOO MANY OF YOU ARE SENDING THEM TO RAYTHEON.



WHAT TH-!? MORE FLIR'S?

RAYTHEON MAY EVENTUALLY GET THEM FOR REPAIR, BUT THEIR FIRST STOP SHOULD BE AT TOBYHANNA FOR ANALYSIS TO SEE JUST HOW MUCH AND WHAT KIND OF REPAIR THEY NEED.

SO, SHIP ALL FAILED FLIR PARTS TO:

Tobyanha Army Depot
11 Hap Arnold Blvd
Bldg 11
Tobyanha, PA 18466-5059

USE DODAAC W25G1W.
USE RIC BYG.



IF YOU HAVE ANY QUESTIONS ABOUT THIS PROCESS, CONTACT
AT DSN 992-7036 OR
(732) 532-7036. OR REACH
HIM BY EMAIL:

us.army.mil